

# VERTICAL MILLING MACHINE

BCIT Asset # Y-05097

Risk Level - **HIGH**

Training and orientation required on this equipment  
Protective Clothing Required  
Students require direct supervision  
Equipment cannot be used unless there is another capable person close by



## Specific Hazards

Getting hair and loose clothing caught and dragged into machine by rotating parts  
Hands or arms getting cut by rotating cutter  
Hands getting cut while changing cutters  
Projectile from Leaving chuck key in chuck or wrench on nut when changing spindle  
Hand or arm crushed when using x axis auto feed  
Hand or arm impacted by handle when using x axis autofeed  
Burnt and/or cut by hot sharp chips during machining  
Pinch points while using the vice  
Part coming loose when machining

## Personal Protective Equipment

