

**BCIT Asset # 13021** 

## **Risk Level - HIGH**

Training and orientation required on this equipment
Protective Clothing Required
Students require direct supervision
Equipment cannot be used unless there is another capable person close by



## **Specific Hazards**

Loose clothing or hair caught
Pinched body part between work piece
and blade
Slips from coolant on floor
Lacerations from sharp cut material edges

## **Personal Protective Equipment**





