

METAL SHEAR

BCIT Asset # N/A

Risk Level - **LOW**

Training and orientation required on this equipment
Protective Clothing Required
Students require minimal supervision



Specific Hazards

Pinching fingers from digits getting crushed in machine

Sharp material edges and corners before and after cutting

Personal Protective Equipment

